



HYUNDAI
Technical Service Bulletin

GROUP Body	NUMBER 21-BD-006H
DATE May, 2021	MODEL(S) Elantra (AD/ADa), Tucson (TL)

SUBJECT: DOOR LATCH REPLACEMENT (WARRANTY EXTENSION TXXL)

Description: Certain Elantra (AD/ADa) and Tucson (TL) vehicles may experience an internal or external door handle being inoperative or requiring repeated attempts to open the door. If this condition occurs, replace the affected door latch.

The warranty coverage for the door latch has been extended to 10 years (unlimited mileage) from the date of original retail delivery or date of first use, whichever occurs first, and is valid for original and subsequent owners.

Applicable Vehicles:

Certain 2017MY Elantra (AD) produced between 11/06/2015 – 12/07/2016
 Certain 2017MY Elantra (ADa) produced between 12/04/2015 – 12/16/2016
 Certain 2016 – 2017MY Tucson (TL) vehicles produced 5/19/2015 – 12/17/2016

Parts Information:

MODEL	PART NAME	PREVIOUS PART NUMBER	NEW PART NUMBER
Tucson (TL)	Latch Assy – Front Door, LH	81310-D3010	81310-D3010FFF
	Latch Assy – Front Door, RH	81320-D3000	81320-D3000FFF
	Latch Assy – Rear Door, LH	81410-D3000	81410-D3000FFF
	Latch Assy – Rear Door, RH	81420-D3000	81420-D3000FFF
Elantra (AD/ADa)	Latch Assy – Front Door, LH	81310-F2030	81310-F2030FFF
	Latch Assy – Front Door, RH	81320-F2010	81320-F2010FFF
	Latch Assy – Rear Door, LH	81410-F2000	81410-F2000FFF
	Latch Assy – Rear Door, RH	81420-F2000	81420-F2000FFF

Warranty Information:

MODEL	OP CODE	OPERATION	OP TIME	CAUSAL PART	NATURE CODE	CAUSE CODE
Tucson (TL)	10D015R0	Door Latch Replacement (1 pc)	0.6 M/H	81310-D3010	I22	ZZ3
	10D015R2	Door Latch Replacement (2 pc)	1.1 M/H	81320-D3000		
	10D015R4	Door Latch Replacement (3 pc)	1.6 M/H	81410-D3000		
	10D015R6	Door Latch Replacement (4 pc)	2.1 M/H	81420-D3000		
Elantra (AD/ADa)	10D015R1	Door Latch Replacement (1 pc)	0.6 M/H	81310-F2030		
	10D015R3	Door Latch Replacement (2 pc)	1.1 M/H	81320-F2010		
	10D015R5	Door Latch Replacement (3 pc)	1.6 M/H	81410-F2000		
	10D015R7	Door Latch Replacement (4 pc)	2.1 M/H	81420-F2000		

Note 1: Submit claim on Campaign Claim Entry Screen


Note 2: If a part that is not covered by this TSB is found in need of replacement while performing this repair for this TSB and the affected part is still under warranty, please submit a separate claim using the same Repair Order. If the affected part is out of warranty, submit a prior approval request for goodwill consideration prior to performing the work.

Note 3: To submit the claim for replacement of 3 or 4 latches, pictures of the door latches being replaced must be attached. Claims submitted where the picture does not have the correct quantity number of latches corresponding with the submitted labor operation code will be subject to charge back. In addition, the parts may be called back by the Warranty Technical Center and the claim will be subject to charge back if the quantity or model of the latches returned do not correspond to the labor operation code.


Service Procedure:

1. Refer to the shop manual sections below for the door latch replacement procedure:

Front Door Latch Replacement



Rear Door Latch Replacement



NOTICE

If 3 or 4 door latches are being replaced, please attach photos of the replaced parts to the claim.

2. The service procedure is now complete.